

Surveying Laboratory

List of Equipments

- Prismatic compass
- Tripod
- Trough compass
- Dumpy level
- Optical square
- Theodolite
- Surveyor's chain
- Ranging rod
- Wooden pegs
- Metallic tape and invar tape
- Level staffs
- Sighting alidade
- Plumbing fork
- Tripod